

IMPORTANT ELECTRICAL EXHIBITING INFORMATION

Exhibitors requiring electrical services should thoroughly read and understand the rules and regulations posted in the Exhibitor Service Kit.

All questions or concerns can be directed to Freeman's electrical department for clarification at +1(773) 379-5040 or faxed to +1(773) 379-5042.

All exhibitor provided equipment for connection to Freeman electrical or for distribution of power within the exhibit may require an inspection to ensure compliance with all Federal, State and Local Codes as listed on the Electrical Order Form.

Exhibitor provided equipment for electrical distribution or equipment connection shall require Freeman to make the final connection from Freeman's power distribution equipment to the exhibit. This is required only to ensure proper voltage and connection prior to energizing any exhibits.

As an exhibitor, should you choose to provide equipment with electrical connectors to plug directly into Freeman electrical equipment, the following list provided will ensure the proper connection:

500 Watts to 2000 Watts - Standard U-Ground 15 or 20 Amp Cord Cap / 515 or 520

20 Amp 120/208 5 Wire - Hubbel Male - HBL 2511 / L2120P

30 Amp 120/208 5 Wire – Hubbel Male – HBL 2811/L2130P

30 Amp Y277 / 480 5 Wire - Hubbel Male - HBL 2821 / L2230P

60 Amp 208v & 480v Daniel Woodhead 5 Wire - Male Y560P

100 Amp 208v & 480v Mini-Cam - Male Leviton 15SDM - Female 15SDF
(Hots – Male Neutral & Ground – Female)

200 / 400 Amp 208v & 480v Large-Cam - Male Hubbel HBL 400PT EKE - Female
Hubbel HBL 400CT (Hots – Male Neutral & Ground – Female)

All of the above listed items may be found at your local electrical wholesale houses. Should you require additional information, please contact Freeman's electrical department.

Hopefully, you find this information useful in planning your event. If we can provide further assistance, please don't hesitate to contact Freeman's electrical department.

We appreciate your business.

F R E E M A N

8201 West 47th St
Mc Cook, IL 60525
(773) 473-7080 Fax: (469) 621-5603

**DISCOUNT PRICE
DEADLINE DATE
MAY 05, 2017**

**INCLUDE THIS FORM
WITH YOUR ORDER
PLEASE USE BLACK INK**

NAME OF SHOW: **2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017**

COMPANY NAME: _____ BOOTH #: _____

ADDRESS: _____ BOOTH SIZE : _____ X

CITY/STATE/ZIP: _____

PHONE: _____ EXT.: _____ FAX #: _____

SIGNATURE: _____ PRINT NAME: _____

CONTACT'S E-MAIL: _____

E-MAIL FOR INVOICE: _____ ☐ Check if you are a new Freeman customer
Invoices will be sent by e-mail; please provide e-mail address of the person who reconciles your invoices if different than contact's email.

METHOD OF PAYMENT

BY SUBMITTING THIS FORM VIA FAX OR POSTAL MAIL OR ORDERING MATERIALS OR SERVICES FROM FREEMAN, YOU AGREE TO BE BOUND BY ALL TERMS & CONDITIONS INCLUDED IN YOUR SERVICE MANUAL.

☐ COMPANY CHECK

Please make check payable to: Freeman
Checks must be in U.S. funds drawn on a U.S. or Canadian bank. ("U.S. FUNDS" MUST BE PRE-PRINTED on Canadian checks.)

Please reference (421867) on your remittance.

☐ CREDIT/DEBIT CARD

For your convenience, we will use this authorization to charge your credit/debit card account for your advance orders, and any additional amounts incurred as a result of show site orders placed by your representative. These charges may include all Freeman companies, or any charges which Freeman may be obligated to pay on behalf of Exhibitor, including without limitation, any shipping charges. Please complete the information requested below:

☐ AMERICAN EXPRESS ☐ MASTER CARD ☐ VISA

We do not accept credit card information via email.

ACCOUNT NO.: _____ EXP. DATE: _____

CARDHOLDER NAME (PRINT): _____ SIGNATURE: _____

CARDHOLDER BILLING ADDRESS: _____

CITY/STATE/ZIP: _____

ENTER TOTALS HERE

FURNISHINGS & ACCESSORIES	CARPET	CLEANING/ SHAMPOOING	PORTER SERVICE	RENTAL EXHIBITS & ACCESSORIES	SIGNS	INSTALLATION LABOR	DISMANTLE LABOR
MATERIAL HANDLING	RIGGING INSTALLATION	RIGGING DISMANTLE	EXHIBIT TRANSPORTATION	HANGING SIGNS	UTILITIES		GRAND TOTAL

- Remember to order in advance to save time and money. You may place your order by phone, fax, mail, or use our online ordering service at: www.freemanco.com/store.
- Orders received without payment or after the discount price deadline date will be charged at the standard price.
- Copies of invoices may be picked up from the Service Desk prior to show closing.
- If you have questions or need assistance with any items not listed, please call and ask for your Exhibitor Services Representative.

F R E E M A N

8201 West 47th St
Mc Cook, IL 60525
(773) 473-7080 Fax: (469) 621-5603

2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017

In order to authorize Freeman to invoice a third party for payment of services rendered to exhibitors, both the exhibiting company and the third party must complete this form and return it at least 14 days prior to show move-in.

EXHIBITING COMPANY AUTHORIZATION OF THIRD PARTY BILLING

"We understand and agree that we, the exhibiting company, are ultimately responsible for payment of charges and agree by submitting this form or ordering materials or services from Freeman, to be bound by all terms and conditions as described in the Terms & Conditions section of this service manual. In the event that the named third party does not discharge payment of the invoice prior to the last day of the show, charges will revert back to the exhibiting company. All invoices are due and payable upon receipt, by either party. The items checked below are to be invoiced to the third party."

BY SUBMITTING THIS FORM VIA FAX OR POSTAL MAIL OR ORDERING MATERIALS OR SERVICES FROM FREEMAN, YOU AGREE TO BE BOUND BY ALL TERMS & CONDITIONS INCLUDED IN YOUR SERVICE MANUAL.

EXHIBITOR NAME: (PLEASE PRINT)

EXHIBITOR SIGNATURE:

DATE:

EXHIBITING COMPANY INFORMATION

EXHIBITING COMPANY NAME:

BOOTH #:

EXHIBITING COMPANY ADDRESS:

CITY/STATE/ZIP:

PHONE:

EXT.

FAX:

CONTACT'S E-MAIL:

Indicate which services are to be invoiced to the Third Party:

☐ ALL FREEMAN SERVICES

☐ FREEMAN EXHIBIT TRANSPORTATION

☐ I&D LABOR/SUPERVISION

☐ RENTAL FURNITURE/CARPET/SIGNS

☐ MATERIAL HANDLING/IN & OUT

☐ BOOTH CLEANING

☐ UTILITIES

☐ OTHER _____

THIRD PARTY COMPANY INFORMATION

THIRD PARTY COMPANY NAME:

CONTACT NAME:

THIRD PARTY BILLING ADDRESS:

CITY/STATE/ZIP:

PHONE:

EXT:

FAX:

CONTACT'S E-MAIL:

E-MAIL FOR INVOICE:

Invoices will be sent by e-mail; please provide the e-mail address of the person who reconciles your invoices if different than contact's e-mail.

THIRD PARTY CREDIT/DEBIT CARD AUTHORIZATION

☐ AMERICAN EXPRESS

☐ MASTERCARD

☐ VISA

FREEMAN NOW ACCEPTS DEBIT CARDS

ACCOUNT NO:

EXP. DATE:

CARDHOLDER NAME (PLEASE PRINT):

CARD TYPE:

AUTHORIZED SIGNATURE:

CARDHOLDER BILLING ADDRESS:

CITY/STATE/ZIP:

PAYMENT & LABOR

YOU ARE ENTERING A CONTRACT WHICH LIMITS YOUR POSSIBLE RECOVERY IN CASE OF LOSS OR DAMAGE.

The terms and conditions set forth below become a part of the Contract between FREEMAN and you, the EXHIBITOR. Acceptance of said terms and conditions will be construed when any of the following conditions are met:

- THE METHOD OF PAYMENT FORM IS SIGNED; OR
- AN ORDER FOR LABOR, SERVICES AND/OR RENTAL EQUIPMENT IS PLACED BY EXHIBITOR WITH FREEMAN; OR
- WORK IS PERFORMED ON BEHALF OF EXHIBITOR BY LABOR SECURED THROUGH FREEMAN.

DEFINITIONS

For purposes of this Contract, "FREEMAN" or "The Freeman Companies" means Freeman Expositions, Inc., Freeman Expositions, Ltd., Freeman Audio Visual, Freeman Exhibit, Freeman Transportation, Hoffend Xposition, Stage Rigging, Inc., Kerry Technical Services, TFC, Inc., Freeman Electrical Services, and their respective employees, directors, officers, agents, assigns, affiliated companies, and related entities including, but not limited to, any subcontractors FREEMAN may appoint. The term "EXHIBITOR" means the Exhibitor, its employees, agents, representatives, and any Exhibitor Appointed Contractors ("EAC").

PAYMENT TERMS

Full payment, including any applicable tax, is due in advance or at show site. All payments must be in U.S. funds and all checks must be drawn on a U.S. bank. Orders received without advance payment or after the deadline date will incur additional After Deadline charges as indicated on each order form. All materials and equipment are on a rental basis for the duration of the show or event and remain the property of FREEMAN except where specifically identified as a sale. All rentals include delivery, installation, and removal from EXHIBITOR'S booth. In case of cancellation of any orders or services by EXHIBITOR, a one-hour "per person, per hour" charge will be applied for all labor orders that are not canceled in writing at least 24 hours prior to the scheduled start time. If Prestige Carpet, Custom-Cut Carpet, Modular Rental Exhibits and any other custom-order items or services have already been provided at the time of cancellation, fees will remain at 100% of the original charge. If the Show or Event is canceled because of reasons beyond FREEMAN'S control, EXHIBITOR remains responsible for all charges for services and equipment provided up to and including the date of cancellation. FREEMAN will not issue refunds to EXHIBITOR of any payments made before the date of cancellation. It is EXHIBITOR'S responsibility to advise the FREEMAN Service Center Representative of problems with any orders, and to check the EXHIBITOR'S invoice for accuracy prior to the close of the Show or Event. If EXHIBITOR is exempt from payment of sales tax, FREEMAN requires an exemption certificate for the State in which the services are to be used. Resale certificates are not valid unless EXHIBITOR is rebilling these charges to its customers. For International EXHIBITORS, FREEMAN requires 100% prepayment of advance orders, and any order or services placed at show site must be paid at the show. For all others, should there be any pre-approved unpaid balance after the close of the show; terms will be net, due and payable in DALLAS, TEXAS upon receipt of invoice. Effective 30 days after invoice date, any unpaid balance will bear a FINANCE CHARGE at the lesser of the maximum rate allowed by applicable law, or 1.5% per month, which is an ANNUAL PERCENTAGE RATE of 18%, and future orders will be on a prepaid basis only. If any finance charge hereunder exceeds the maximum rate allowed by applicable law, the finance charge shall automatically be reduced to the maximum rate allowed, and any excess finance charge received by FREEMAN shall be either applied to reduce the principal unpaid balance or refunded to the payer. If past due invoices or invoice balances are placed with a collection agency or attorney for collection or suit, EXHIBITOR agrees to pay all legal and collection costs. THESE PAYMENT TERMS AND CONDITIONS SHALL BE GOVERNED BY AND CONSTRUED IN ACCORDANCE WITH THE LAWS OF THE STATE OF TEXAS. In the event of any dispute between the EXHIBITOR and FREEMAN relative to any loss, damage, or claim, such EXHIBITOR shall not be entitled to and shall not withhold payment, or any partial payment, due to FREEMAN for its services, as an offset against the amount of any alleged loss or damage. Any claims against FREEMAN shall be considered a separate transaction, and shall be resolved on its own merits. FREEMAN reserves the right to charge EXHIBITOR for the difference between the EXHIBITOR'S estimate of charges and the actual charges incurred by EXHIBITOR, or for any charges that FREEMAN may be obligated to pay on behalf of EXHIBITOR, including without limitation, any shipping charges. If EXHIBITOR provides a credit card for payment and charges are rejected by the EXHIBITOR'S credit card company for any reason, FREEMAN hereby provides notice that it reserves the right, and EXHIBITOR authorizes FREEMAN, to continue to attempt to secure payment through that credit card for as long as unpaid balances remain on the EXHIBITOR'S account. In the event that a THIRD PARTY orders on behalf of the EXHIBITOR and the named THIRD PARTY does not discharge payment of the invoice prior to the last day of the show, charges will revert back to the EXHIBITOR. All invoices are due and payable upon receipt, by either party.

ELECTRICAL

Claims will not be considered, or adjustments made unless filed in writing, by Exhibitor, prior to the close of the event. Freeman is not responsible for any damage or loss caused by the loss of power beyond its control and Exhibitor agrees to hold Freeman, its officers, directors, employees and agents harmless from such power loss. IN NO EVENT SHALL FREEMAN BE LIABLE FOR ANY INDIRECT OR CONSEQUENTIAL DAMAGES (INCLUDING WITHOUT LIMITATION LOST PROFITS) EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, WHETHER UNDER THEORY OF CONTRACT, TORT (INCLUDING NEGLIGENCE), PRODUCTS LIABILITY OR OTHERWISE. Exhibitor shall indemnify and hold harmless Freeman, its officers, directors, employees, and agents from and against any and all claims, liabilities, damages, fines, penalties or costs of whatsoever nature (including reasonable attorneys' fees) arising out of or in any way connected with Exhibitor's actions or omissions under this Agreement.

LABOR UNDER THE SUPERVISION OF EXHIBITOR RESPONSIBILITIES

EXHIBITOR shall be responsible for the performance of labor provided under this option. It is the responsibility of EXHIBITOR to supervise labor secured through FREEMAN in a reasonable manner as to prevent bodily injury and/or property damage and also to direct them to work in a manner that is in compliance with FREEMAN'S Safe Work Rules and/or Federal, State, County and Local ordinances, rules and/or regulations, including but not limited to Show or Facility Management rules and/or regulations. It is the responsibility of EXHIBITOR to check in with the Service Desk to pick up labor, and to return to the Service Desk to release labor when the work is completed.

INDEMNIFICATION

EXHIBITOR agrees to indemnify, hold harmless, and defend FREEMAN from and against any and all demands, claims, causes of action, fines, penalties, damages, liabilities, judgments, and expenses (including but not limited to reasonable attorneys' fees and investigation costs) for bodily injury, including any injury to FREEMAN employees, and/or property damage arising out of work performed by labor provided by FREEMAN but supervised by EXHIBITOR. Further, the EXHIBITOR'S indemnification of FREEMAN includes any and all violations of Federal, State, County or Local ordinances, "Show Regulations and/or Rules" as published and/or set forth by Facility or Show Management, and/or directing labor provided by FREEMAN to work in a manner that violates any of the above rules, regulations, and/or ordinances.

IMPORTANT


PLEASE REFER TO FREEMAN'S "MATERIAL HANDLING TERMS & CONDITIONS" AS IT RELATES TO MATERIAL HANDLING SERVICES AND TO THE "SERVICE REQUEST & SHIPPING INSTRUCTIONS CONTRACT" AS IT RELATES TO TRANSPORTATION SERVICES. CONTRACT TERMS DEPEND ON THE NATURE OF SERVICES SECURED BY EXHIBITOR THROUGH FREEMAN. TERMS & CONDITIONS MAY VARY FOR EACH TYPE OF SERVICE ORDERED THROUGH FREEMAN.


ELECTRICAL SERVICES

40 x 40 use 1 square = 1 foot

SAMPLE LAYOUTS


INLINE BOOTHS

Power is run or dropped to inline booths along the back walls or drape line of multi booth sections. The “main power locations” therefore are always located at the back of inline and peninsula booths. Outlets may not be in the exact center of the back wall. 120 volt outlets are shared by back to back booths. Example: Outlet = 




Electrical layouts are required whenever an outlet is needed at any other location within the booth except for the back wall. Exact measurements and/or comments that clearly indicate outlet locations **must be included**. Examples based on above floor plan:

20 x 20 Peninsula – Booth # 401
Order = 2-10 amp, 1-20 amp outlets



10 x 20 Inline – Booth # 409
Order = 2 x 5 amp outlets



ISLAND BOOTHS

Electrical layouts are always required for island booths and **must include** the following information:

1. Main Drop.

Since there is no back wall in an island, the exhibitor supplies the location of the main drop, whether one or multiple outlets are ordered. When it will be the point from which power will be distributed to other outlets in the booth, a panel or other piece of electrical equipment will be installed at the main drop. For this reason, it is recommended that main drops be located in a closet, under a table/desk or in another area that keeps it out of sight. Measurements must be provided to the main drop.


2. Location and load of all outlets.

Again, dimensions must be provided to all satellite outlets along with the load of each outlet. It is best to indicate voltage, phase and amperage for all outlets once an order exceeds 120 volt service.

3. Booth orientation.


Providing reference points such as surrounding aisle and/or booth numbers defines how an island booth is oriented to the overall show floor plan. In other words, which side is which? It is best to draw your layout relative to the show floor plan so that both are facing the same direction. Examples:

Section of show floor plan



20 x 20 Island – Booth # 401

Order = 1 x 208 volt, 3 phase, 10 amp + 120 volt, 2 x 20 amp + 2 x 5 amp outlets



ELECTRICAL USAGE GUIDE

The following wattages are approximate and are provided to help you estimate your power usage. We recommend that you refer to a specification sheet or the electrical stamp or label usually located on the back or bottom of any electrical apparatus and order one outlet for each piece of equipment to avoid tripping/power outages during the event.

100 WATTS = 1 AMP

WATTAGE		WATTAGE	
Blender	1000	Imprinter for T-Shirts	2000
Can Opener	500	Iron	700 - 1100
Credit Card Reader / Lead Retrieval	100	Juicer	
Cash Register	100 - 200	Single	500
Coffee Pot		Double	1000
Household size	1200	Laminator	2000
Large Brewer	1500 - 2000	Lead Retrieval / Card Reader	100
Computers		Lights with Freeman rental booths	200 each
Desk Top (monitor & CPU)	200 - 900	Microwave Oven	500 – 2000
Lap Top	150 - 300	Mixer	500 – 1000
Monitor (independent)	50 - 200	Photocopier	dependent upon size – may require 208v
Computer Printer		Pizza Oven (small)	30 amp/120 volt Special Connection
Dot Matrix	100 - 500	Plasma TV – 32" to 50"	1000
Laser	400 - 1000	Popcorn Maker	2000
Crock Pot	200 -1000	Projector (May be dependent upon size)	1000
DVD Player	100	Refrigerator	
Electric Frying Pan	1200 - 2000	Small	100
Fax Machine	1000	Regular	700
Food Processor	500 – 2000	Meat Slicer	500 - 1000
Glue Gun	300	Steamer	2000
Griddle	1500	Stereo (amplifier)	100 - 500
Hair Dryer	1000 - 1900	Television	100 - 500
Heat Lamps (per lamp)	250	Toaster	1000
Heater (portable)	1500 - 2000	Toaster Oven	1500
Hot Plate		Typewriter	100
Single	1000	Vacuum Cleaner	1500
Double	1500 – 2000	Water Cooler	100
Hot Water Heater	30 amp/208 volt/Single Phase		

F R E E M A N

8201 West 47th Street
McCook, Illinois 60525
(773) 473-7080 • Fax (469) 621-5603
Email: FreemanChicagoES@freemanco.com

DISCOUNT PRICE
DEADLINE DATE
MAY 5, 2017

**INCLUDE THE FREEMAN METHOD OF
PAYMENT FORM WITH YOUR ORDER**

NAME OF SHOW: **2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017**

COMPANY NAME: _____ BOOTH #: _____

CONTACT NAME: _____ PHONE #: _____

E-MAIL ADDRESS: _____

For Assistance, please email our experts at chicagoelectrical@freemanco.com or call 773-473-7080.

For fast, easy ordering, go to www.freemanco.com/store

ELECTRICAL LABOR

LABOR RATES & SCHEDULE:

Straight Time - 8:00 am - 4:30 pm Monday through Friday (Excluding Holidays)

Overtime - 4:30 pm to Midnight Monday through Friday; First (8) hours at work on Saturday up to 4:30 pm.

Double Time - After (8) hours at work on Saturday, or after 4:30 pm on Saturday; regardless of starting time.

ALL DAY Sunday and Holidays and Midnight to 6:00 am Monday through Friday

Straight Time, Overtime and Double Time Labor Invoicing will be in compliance per MPEA Legislation.

Description	Advance Price	Show Site Price
Electrician - ST.....	\$104.00	\$145.75
Electrician - OT	\$152.00	\$213.00
Electrician - DT	\$201.00	\$281.50
Scissor Lift w/crew - ST	\$303.50	\$425.00
Scissor Lift w/crew - OT	\$351.50	\$492.25
Scissor Lift w/crew - DT	\$400.50	\$560.75
Condor w/crew - ST	\$471.00	\$659.50
Condor w/crew - OT.....	\$569.00	\$796.75
Condor w/crew - DT.....	\$668.00	\$935.25

Dismantle labor will be charged at 50% of the total install time rounded to the next half hour.

• Show site price applies to all labor orders placed at show site.

• Start time guaranteed only at start of working day.

Review the list of work below to determine if electrical labor is required in your booth. None of the following services may be performed by other Unions or I & D houses as it falls under electrical jurisdiction. Time and material charges will apply. Please visit the Freeman service desk to confirm that you are ready for service.

Note: For more information and an example of a completed floorplan please see the following page.

FLOOR WORK:

Floor work is the distribution of electrical under carpet and flooring.

☐ **OK TO PROCEED WITHOUT EXHIBITOR PRESENT:**

Complete Before: Date _____ Time _____

Work is completed prior to your arrival. Freeman must receive detailed blue prints/floor plans for power distribution under carpet.

PRINT NAME: _____

AUTHORIZED SIGNATURE: _____

☐ **EXHIBITOR SUPERVISION (DO NOT PROCEED):**

Date _____ Time _____ # of Electricians _____

NAME OF ON-SITE CONTACT: _____

CELL PHONE: _____

Special Instructions: _____

BOOTH WORK:

Booth work is any of the following. Please check all that apply:

- ☐ Distribution of electrical overhead (more than one drop location in your booth).
- ☐ Distribution of electrical through booth structure.
- ☐ Mounting of plasmas/LCD monitors and lights.
- ☐ Connection or hard wiring of all exhibitor equipment.
- ☐ Lighting used as spot or flood lights.
- ☐ Assembly and installation of all lighting from truss or beams (including assembly and hanging of truss).
- ☐ Wiring of overhead signs.
- ☐ Installation of electrical headers and/or light boxes.
- ☐ Other _____

Labor Request

Date _____ Time _____ Est. # Hours _____ # Electrician _____

Date _____ Time _____ Est. # Hours _____ # Electrician _____

Date _____ Time _____ Est. # Hours _____ Lift Type _____

NAME OF ON-SITE CONTACT: _____

CELL PHONE: _____

Special Instructions: _____

ELECTRICAL INSTRUCTIONS

- 1 Labor rates are based on current wage scales and are subject to change in the event of a wage increase after rates have been published.
- 2 A minimum charge of one half (1/2) hour is applicable to all labor requests. Additional time on the same day is billed in 1/2 hour increments. Continuations to another day are a minimum of one half (1/2) hour.
- 3 Labor must be picked up at the Freeman service desk. Charges for labor commence at time of dispatch to service the labor call. A one half (1/2) hour minimum will apply if an exhibitor representative is not present at the time of call or reschedules the call, unless 24 hour advance notice is received in writing.
- 4 Labor charges will include the time for electricians to gather the necessary tools and material for the job, have their work checked by the client and return the tools and material to the supply area.
- 5 Exhibitors may supply their own 14 gauge 3 wire, extension cords and/or power strips, both of which must be grounded and UL approved.


CANCELLATION POLICY

A 50% refund will be applied to electrical outlets cancelled after installation. Refunds will not be issued for materials and/or labor charges related to the installation.

EXAMPLE OF PLAN AND INFORMATION REQUIRED TO COMPLETE FLOORWORK

Please indicate the following on the floor plan.

1. Location and load of main power drop - please provide specific dimensions and wattages/amperages.
2. Location and load of all outlets - please provide specific dimensions and wattage, amperage and voltage.
3. Booth orientation - please provide surrounding aisle and/or booth numbers.



F R E E M A N

8201 West 47th Street
McCook, IL 60525

(773) 473-7080 • Fax (469) 621-5603

Email: FreemanChicagoES@freemanco.com

**DISCOUNT PRICE
DEADLINE DATE
MAY 5, 2017**

**INCLUDE THE FREEMAN METHOD OF
PAYMENT FORM WITH YOUR ORDER**

NAME OF SHOW: **2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017**

COMPANY NAME: _____ BOOTH #: _____

CONTACT NAME: _____ PHONE #: _____

E-MAIL ADDRESS: _____

For Assistance, please email our experts at chicagoelectrical@freemanco.com or call 773-473-7080.

For fast, easy ordering, go to www.freemanco.com/store

ELECTRICAL OUTLETS (Double Price for 24 Hour Service)

Power includes delivery of the service to one location at the rear of the booth in peninsula and inline booths. Please see the Electrical Labor order form for rates and instructions if you require outlets in other locations, have lights or electrical items to hang or erect, have orders for power of 208v or higher, or have other electrical requirements.

110/120 VOLT

	Quantity (For Show Hours Only)	Quantity (For 24 hrs/day Double Price)	Discount	Standard	
	Show	24 Hr.	Price	Price	TOTAL
500 Watts (5 amps)	_____	_____	117.50	176.25 = \$	_____
1000 Watts (10 amps)	_____	_____	208.00	312.00 = \$	_____
2000 Watts (20 amps)	_____	_____	323.00	484.50 = \$	_____

208 VOLT SINGLE PHASE (Labor Required for Connection)

20 Amps	_____	_____	520.00	780.00 = \$	_____
30 Amps	_____	_____	548.00	822.00 = \$	_____
60 Amps	_____	_____	599.00	898.50 = \$	_____
100 Amps	_____	_____	1,199.00	1,798.50 = \$	_____

208 VOLT THREE PHASE (Labor Required for Connection)

20 Amps	_____	_____	643.00	964.50 = \$	_____
30 Amps	_____	_____	717.00	1,075.50 = \$	_____
60 Amps	_____	_____	776.00	1,164.00 = \$	_____
100 Amps	_____	_____	1,264.00	1,896.00 = \$	_____
200 Amps	_____	_____	2,526.00	3,789.00 = \$	_____
400 Amps	_____	_____	4,346.00	6,519.00 = \$	_____

Transformer to Boost 208V to Approx. 230V - \$7.50 per Amp (20 Amp Min.)

Qty of Amps _____ X Price \$ _____ = \$ _____

480 VOLT THREE PHASE (Labor Required for Connection)

20 Amps	_____	_____	784.00	1,176.00 = \$	_____
30 Amps	_____	_____	826.00	1,239.00 = \$	_____
60 Amps	_____	_____	1,121.00	1,681.50 = \$	_____
100 Amps	_____	_____	1,292.00	1,938.00 = \$	_____
200 Amps	_____	_____	2,583.00	3,874.50 = \$	_____

LIGHTING (Price Includes Power & Labor for Installation)

Single Light Stand (200w)	_____	159.00	238.50 = \$	_____
Double Light Stand (400w)	_____	245.00	367.50 = \$	_____
Arm Light	_____	153.50	230.25 = \$	_____
Overhead Quartz Light*	_____	466.00	699.00 = \$	_____

*Overhead quartz lights include labor and equipment to install and first focus.

*May require labor and/or lift at additional charge. Please contact chicagoelectrical@freemanco.com for estimated charges.

For single or double light stand; price includes installation along the side rails of an inline booth. Placement elsewhere will require additional labor and materials.

ADDITIONAL INFORMATION

FOR ADVANCE PAYMENT PRICE

Your order with full payment along with a floor plan indicating main power location and distribution points, if applicable, must be received prior to:

**DEADLINE DATE OF:
MAY 5, 2017**

MULTIPLE OUTLET LOCATIONS / ISLAND BOOTHS

A scaled floor plan is required for orders with multiple outlet locations and/or island booths. Detailed examples are provided on the following page. If a power location or main drop in an island booth is not provided prior to show move-in, a location will be determined by Freeman in order to maintain delivery schedules. Relocation of the service will be charged on a time and material basis.

ISLAND BOOTHS

For island booths with no labor ordered, there is a 1/2 hour minimum installation charge and a 1/2 hour minimum dismantle charge.

INLINE AND PENINSULA BOOTHS

Power will be placed in the back of the booth unless otherwise specified.

24 HOUR SERVICES

If an uninterrupted power supply is required for the full duration of the show, please order 24 hour power. Electricity is turned on 30 minutes prior to show opening and turned off 30 minutes after show closes on show days. Power will be turned off immediately after final show closing. If you require power outside actual show hours, special arrangements should be made in advance. Additional charges may apply.

SEPARATE OUTLETS

Separate outlets should be ordered for each piece of equipment and/or each power location.

CANCELLATION

A 50% refund will be applied to electrical services cancelled after installation. Refunds will not be issued for materials and/or labor charges related to the installation.

OVERHEAD POWER

If you require your power from overhead, additional materials and labor may be incurred. Please contact chicagoelectrical@freemanco.com.

EXTENSION CORDS AND POWER STRIPS

Extension cords and power strips are available for rental at the Freeman Service Desk. Extension cords and power strips owned and used by Exhibitors MUST comply with the City of Chicago Electrical Code. Please contact us for additional information.

TOTAL COST

Outlet(s)	\$ _____
Lighting	\$ _____
Tax 9% Rental	\$ _____
GRAND TOTAL	\$ _____

FREEMAN electrical

ELECTRICAL INSTRUCTIONS

HOW TO DETERMINE ELECTRICAL REQUIREMENTS

For Equipment

All electrical equipment is stamped or labeled with electrical ratings usually found on the back or bottom of the equipment. Verify voltage and either amperage or wattage from the information provided. Standard office and household items operate on 110/120 volt power. Machinery and equipment typically require 208 or 480 volt power.


For Lighting

Verify the wattage of the bulbs in the lights and multiply by the number of bulbs/lights.


LOCATION OF POWER IN YOUR BOOTH

In-Line and Peninsula Booths

Power will be installed in one location, typically on the floor somewhere along the back of the booth, as indicated in the following diagrams: (We cannot guarantee that the outlet will be specifically located in the middle.)



IN-LINE BOOTHS / PENINSULA




BACK TO BACK PENINSULA


If power is required in locations other than indicated above, secondary distribution will be required and billed on a time and material basis. Please complete and submit an Electrical Labor Order Form with your power order, along with a floor plan as described below.

Island Booths/Multiple Outlets

Floor plans are always required for Island Booths and orders for multiple outlet locations. The floor plan must indicate booth dimensions, surrounding booth numbers for orientation within the facility, each outlet location, required wattage or amperage and location for main drop. If power location in an island booth is not provided prior to show move-in, a location will be determined by Freeman in order to maintain delivery schedules. Relocation of the service will be charged on a time and material basis. See examples below: A grid is available at freemanco.com to print as a base layout.



Island Booth with one outlet



10 X 20 Booth with multiple outlets
Labor Required

OTHER:

1. Labor is required for any and all electrical work over and above the installation of the main power drop. Please see the Electrical Labor form for complete details. Please complete the labor order form.
2. Dismantle labor will be automatically charged at 50% of the installation time and rounded to the nearest half hour.
3. All material and equipment provided by Freeman is for rental purposes only and remains the property of Freeman. All equipment will be removed at the close of the show by Freeman.
4. All equipment regardless of power source, must comply with Federal, State and local codes. Freeman reserves the right to inspect all electrical devices and connections to ensure compliance with all codes. Freeman is required to refuse connections where the exhibitor wiring is not in accordance with local electrical code.
5. Standard wall and other permanent building utility outlets or sockets are not part of booth space and may not be used by exhibitors unless electrical services have been ordered.
6. Exhibitors' cords must be a minimum of 14 gauge 3 wire with ground and must be flat when used for floorwork. All multi-outlet devices (eg - power strips) must have circuit protection. All exposed non-current carrying metal parts of fixed equipment, which are liable to be energized, shall be grounded.
7. Exhibitors' equipment will be modified to conform to Freeman receptacles. Labor and materials to install or change a cord cap will be billed on a time and material basis.
8. Exhibitors with hardwall displays must arrange for power to be installed inside the booth or provide access.
9. Power sharing is not permitted between exhibitors.

F R E E M A N

8201 West 47th Street
McCook, Illinois 60525
(773) 473-7080 • Fax (469) 621-5603
Email: FreemanChicagoES@freemanco.com

DISCOUNT PRICE
DEADLINE DATE
MAY 5, 2017

**INCLUDE THE FREEMAN METHOD OF
PAYMENT FORM WITH YOUR ORDER**

NAME OF SHOW: **2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017**

COMPANY NAME:

BOOTH #:

CONTACT NAME:

PHONE #:

E-MAIL ADDRESS:

For Assistance, please email our experts at chicagoelectrical@freemanco.com or call 773-473-7080.

For fast, easy ordering, go to www.freemanco.com/store

HANGING TRUSS & THEATRICAL LIGHTING EQUIPMENT AND LABOR

- All rigging must comply with MPEA and Show Management rules and regulations and facility limitations.
- All overhead rigging and flown objects must be assembled and disassembled by FREEMAN. Exhibitor's display company and/or I & D representatives may supervise only and will not be allowed to assemble/disassemble or install and remove rigging or flown objects. No one other than Freeman employees will be permitted in lifts.
- FREEMAN requires an engineered print of all truss and lighting rigging, including rigging point loads per our facility agreement. Failure to provide a DWG file of the rigging plot with load and required information three (3) weeks prior to move-in may prohibit your rig from being hung.
- All electrical components provided by outside vendors are considered freight and may be subject to material handling charges.
- Time will commence per exhibitors request. Failure to start at the requested time will result in a 4 hour minimum charge per labor person requested, unless 24-hour advance notice is provided in writing.
- Freeman labor installs/dismantles all programmable dimmable lighting fixtures, video walls, audio, and projection equipment.
- For Pre Rigging: Please contact FREEMAN for availability.

Straight Time: 8:00 A.M. to 4:30 P.M. Monday through Friday

Overtime: 4:30 P.M. to Midnight Monday through Friday; First (8) hours at work on Saturday up to 4:30 P.M.

Double Time: After (8) hours at work on Saturday, or after 4:30 P.M. on Saturday; regardless of starting time.

ALL DAY Sunday and Holidays and Midnight to 6:00 a.m. Monday through Friday

• Straight Time, Overtime and Double Time Labor Invoicing will be in compliance per MPEA Legislation.

LIGHTING DESIGNER INFORMATION:

Name: _____ Phone: () _____

Company Name: _____

Description	Advance Price	Standard Price
RIGGING EQUIPMENT		
• Rates are per lift and crew, per hour		
Condor crew consists of 1 Operator and 1 Ground Man		
Condor and Crew - ST	471.00	659.50
Condor and Crew - OT	569.00	796.75
Condor and Crew - DT	668.00	935.25
Scissor Lift consists of 1 Operator ONLY		
Scissor Lift and Operator - ST	303.50	425.00
Scissor Lift and Operator - OT	351.50	492.25
Scissor Lift and Operator - DT	400.50	560.75
RIGGING LABOR (high riggers, ground riggers and electricians)		
Please contact Freeman Exhibitor Services at (773) 473-7080 for details.		
Electrical Rigger - ST	\$104.00	\$145.75
Electrical Rigger - OT	152.00	213.00
Electrical Rigger - DT	201.00	281.50
MISCELLANEOUS LABOR		
• Charges do not apply if your electrical needs consist of 20 amps or less.		
Turn-On / Turn-Off Charge - ST	\$104.00	\$145.75
Turn-On / Turn-Off Charge - OT	152.00	213.00
Turn-On / Turn-Off Charge - DT	201.00	281.50
MISCELLANEOUS EQUIPMENT		
One Ton Hoist (power not included - complete Electrical Order Form)	\$ 516.00	\$ 774.00
Half Ton Hoist (power not included - complete Electrical Order Form)	497.00	745.50
20.5" Box Truss (per foot) - Silver	25.00	\$ 37.50
12" x 18" Box Truss (per foot) - Black	24.00	\$ 36.00
12" Box Truss (per foot) - Silver	23.00	\$ 34.50
Small Rotator	261.50	\$ 392.25
Large Rotator	521.00	\$ 781.50
Design Fee	153.00	\$ 153.00
Corner Blocks	104.00	\$ 156.00

***Please attach a detailed production schedule that includes a
daily list of labor and equipment needed for the duration of the show.***

NAME OF SHOW: **2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017**

COMPANY NAME: _____ BOOTH #: _____

CONTACT NAME: _____ PHONE #: _____

E-MAIL ADDRESS: _____

For Assistance, please email our experts at chicagoelectrical@freemanco.com or call 773-473-7080.

For fast, easy ordering, go to www.freemanco.com/store

HANGING TRUSS & THEATRICAL LIGHTING EQUIPMENT AND LABOR

INSTALLATION LABOR

☐ **SUPERVISION BY FREEMAN ELECTRIC RIGGING LABOR**

Please complete the information on the reverse side

- Installation of your exhibit will be completed at our discretion prior to show opening.
- The charge for this service is the total installation labor bill, with **\$120.00 per hour charge**.

Emergency Contact: _____ Phone Number: _____

☐ **SUPERVISION BY EXHIBITOR PERSONNEL**

Supervisor will be: _____ Phone Number: _____

Date	Time	No. of People	Approx. Hours	Total Hours	Hourly Rate	Total Estimated Cost
_____	_____	_____	x _____	= _____	@ \$ _____	= \$ _____
_____	_____	_____	x _____	= _____	@ \$ _____	= \$ _____
Freeman Supervision (\$120.00)						= \$ _____
Total Installation						= \$ _____

DISMANTLE LABOR

☐ **SUPERVISION BY FREEMAN ELECTRIC RIGGING LABOR**

Please complete the information on the reverse side

- Freeman is not responsible for product or literature that is not properly packed and labeled by exhibitor.
- The charge for this service is the total dismantle labor bill, with **\$120.00 per hour charge**.

Emergency Contact: _____ Phone Number: _____

☐ **SUPERVISION BY EXHIBITOR PERSONNEL**

Supervisor will be: _____ Phone Number: _____

Date	Time	No. of People	Approx. Hours	Total Hours	Hourly Rate	Total Estimated Cost
_____	_____	_____	x _____	= _____	@ \$ _____	= \$ _____
_____	_____	_____	x _____	= _____	@ \$ _____	= \$ _____
Freeman Supervision (\$120.00)						= \$ _____
Total Dismantle						= \$ _____

PLEASE NOTE:

IF EXHIBITOR APPOINTED CONTRACTOR (EAC) DOES NOT SHOW UP AT THE DESIGNATED TIME, THE CLIENT COULD BE RESPONSIBLE FOR THE ORDERED ELECTRICAL LABOR.

FREEMAN hanging truss & chain hoist

F R E E M A N

8201 West 47th Street
McCook, Illinois 60525
(773) 473-7080 • Fax (469) 621-5603
Email: FreemanChicagoES@freemanco.com

DISCOUNT PRICE
DEADLINE DATE
MAY 5, 2017

**INCLUDE THE FREEMAN METHOD OF
PAYMENT FORM WITH YOUR ORDER**

NAME OF SHOW: **2017 ASCO ANNUAL MEETING / JUNE 3 - 5, 2017**

COMPANY NAME:

BOOTH #:

CONTACT NAME:

PHONE #:

E-MAIL ADDRESS:

For Assistance, please email our experts at chicagoelectrical@freemanco.com or call 773-473-7080.

For fast, easy ordering, go to www.freemanco.com/store

LIGHTS OUT REQUEST

All exhibitors may request the lights located directly over their booth be turned off. Shrouding of lights (fabric hung around light to screen light from certain areas) and turning off of individual lights are done on a time, material and equipment basis. For the purposes of lights out, there are three categories of requests:

- 1. Over Booth** - Lights directly over exhibitor's booth. This request should be done in advance.
- 2. Partial Over Booth** - Lights partially over exhibitor's booth and partially over adjacent aisle or exhibitor.
- 3. Adjacent Aisle Lights** - Lights completely over adjacent aisle. The exhibitor that is closest to the light has the right to determine if the light may be turned off. However, the final decision for any lights being turned off always reverts to Show Management and the Fire Safety Office.

Freeman and Show Management cannot confirm lights out categories 2 or 3 until all affected exhibitors are on site. Lights in categories 2 and 3 must be approved by Show Management and Fire Safety officials. Category 3 lights must also be approved by affected neighboring exhibitors. In these instances, lights in question may possibly be shrouded.

INSTRUCTIONS

- All eligible companies must submit the "Lights Out Request" to Show Management and Freeman by MAY 5, 2017. With the completion of this form, the exhibitor accepts any applicable charges associated with this request.
- The MCC lighting system is set up in light banks of two (2) lights and/or individual circuits depending upon the location in the hall.
- Lights in the East, North & South Exhibit Hall may require a condor and crew to turn lights off.
- It may not be possible to turn off individual lights without turning off all lights in a particular bank.
- If the lights you have requested to be turned off are in a bank of lights, it may be possible to delete individual lights if accessible.

ASSISTANCE

- For questions regarding the placement and number of lights above your booth, please contact the Freeman Electrical Department at (773) 473-7080.
- To determine whether a condor and crew will be needed, please contact the Freeman Electrical Department at (773) 473-7080.

LIGHTS OUT REQUEST

Please Note: If you have requested that a bank of two (2) lights be shut off, you will be charged for two (2) lights - **not** one (1) bank.

___ Lights Shrouded @ \$78.00 per light = \$ _____

___ Individual Lights Turned Off @ \$67.50 per light = \$ _____

Light Numbers: _____ Date Required: _____ Time Required: _____

LIGHTS REQUIRING CONDOR

Please Note: Shrouding requests will require a condor. Please see rates below. (Rates do not include materials.)

	DISCOUNT PRICE	SHOW SITE PRICE
Condor and crew Straight Time (per hour).....	\$471.00	\$659.50
Condor and crew Overtime (per hour).....	\$569.00	\$796.75
Condor and crew Doubletime (per hour).....	\$668.00	\$935.25

ESTIMATE CONDOR CHARGES

Approx Hours Hourly Rate Total Estimated Cost

_____ @ _____ = _____

Light Numbers: _____ Date Required: _____ Time Required: _____

Total: _____ x Tax (9%) _____ = _____

(421867)

FREEMAN lights out/shrouding request

F R E E M A N

8201 West 47th Street
McCook, IL 60525
(773) 473-7080 • Fax (469) 621-5603
Email: FreemanChicagoES@freemanco.com

IMPORTANT INFORMATION - PLEASE READ PRIOR TO ORDERING

HANGING TRUSS & LIGHTING EQUIPMENT

OFFICIAL ELECTRICAL CONTRACTOR RESPONSIBILITIES

- Freeman personnel/employees must operate all chain motors, including the final trim.
- Freeman personnel/employees only will be allowed in aerial lifts.
- Freeman personnel/employees only will be allowed to operate mechanized equipment.
- Freeman personnel/employees must assemble and disassemble any and all overhead rigging. This includes, but is not limited to:
 - * The assembly of all truss
 - * The attachment and disassembly of light fixtures to truss
 - * The installation and dismantle of power sources, programmable dimmable lighting packages, chain motors and span sets.
- The Electrical Contractor will run all initial power sources and Freeman personnel will make all connections to the dimmable power sources.
- Freeman Electricians install/dismantle all programmable dimmable lighting fixtures, video walls, audio, and projection.

PLACING YOUR ORDER (please include these items when placing your order)

- Complete the Method of Payment
- Complete the Hanging Truss & Chain Hoist Order Form
- Complete the Electrical Order Form for chain hoist power
- Complete the Electrical Labor Order Form for chain hoist power
- Include Rigging Plot in a DWG format with the order forms - plot must reflect the following:
 1. Hang point locations
 2. Height above the floor of each hang point
 3. Weight that will be suspended from each hang point
 4. Exhibit plan showing the location of the hang points and the structure as it pertains to the exhibit plan
- **Complete the Structural Integrity Statement.**
- Send the above information to Freeman at the address on the order forms

GROUND-SUPPORTED TRUSS & LIGHTING EQUIPMENT

OFFICIAL ELECTRICAL CONTRACTOR RESPONSIBILITIES

- Freeman Electricians will provide installation and dismantle labor of self-climbing and/or mechanized truss systems.
- Freeman Electricians must install and dismantle any programmable dimmable lighting fixtures that are attached to any ground-supported truss.
- Freeman Electricians must assemble and disassemble as well as install and dismantle all electrical hanging signs.

PLACING YOUR ORDER (please include these items when placing your order)

- Complete the Method of Payment
- Complete the Hanging Truss & Chain Hoist Order Form
- **Complete the Structural Integrity Statement**
- Send the above information to Freeman at the address on the order forms

IMPORTANT INFORMATION (continued)

NON-ELECTRICAL HANGING SIGNS (UNDER 250 POUNDS)

OFFICIAL ELECTRICAL CONTRACTOR RESPONSIBILITIES

- Freeman personnel/employees must assemble and disassemble, install and dismantle all hanging signs.

PLACING YOUR ORDER (please include these items when placing your order)

- Complete the Method of Payment
- Complete the Hanging Sign Order Form
- Include Assembly Instructions
- **Complete the Structural Integrity Statement**
- Ship sign to Freeman warehouse using the "Hanging Sign" shipping labels provided
- Send the above information to Freeman at the address on the order forms

NON-ELECTRICAL HANGING SIGNS

(OVER 250 POUNDS - CHAIN HOIST OR FALL IS REQUIRED)

OFFICIAL CONTRACTOR RESPONSIBILITIES

- Freeman personnel/employees must assemble and disassemble all hanging signs.
- Freeman personnel/employees must install and dismantle all hanging signs.

PLACING YOUR ORDER (please include these items when placing your order)

- Complete the Method of Payment
- Complete the Hanging Sign Order Form
- Complete the Hanging Truss & Chain Hoist Order Form
- Complete the Electrical Order Form for chain hoist power
- Complete the Electrical Labor Order Form for chain hoist power
- Include Assembly Instructions
- All rigging plans must be submitted in a DWG format to Freeman Rigging Manager three (3) weeks prior to move-in.
- **Complete the Structural Integrity Statement**
- Ship sign to Freeman warehouse using the "Hanging Sign" shipping labels provided
- Send the above information to Freeman at the address on the order forms

ELECTRICAL HANGING SIGNS

OFFICIAL ELECTRICAL CONTRACTOR RESPONSIBILITIES

- Electrical contractor will assemble and disassemble all electrical hanging signs.
- Electrical contractor will install and dismantle all electrical hanging signs.
- Electrical contractor will install chain hoist and attach sign to the hoist for signs over 250 pounds.
- Power for chain hoist must be included with your order for electrical services.

PLACING YOUR ORDER (please include these items when placing your order)

- Complete the Hanging Sign Order Form
- Complete the Electrical Labor Order Form
- Complete the Electrical Services Order Form
- Include Assembly Instructions
- **Complete the Structural Integrity Statement**
- Ship sign to Freeman warehouse using the "Hanging Sign" shipping labels provided.
- Send the above information to electrical contractor at the address on the order forms